Vehicle Inspection Report

File data 126080746 - 0

Manufacturer	AUDI
Model	Q3/SQ3 (F3) 5P/SPORTBACK (18-)
Plate number	2065LYF
VIN	WAUZZZF32N1107567
Color	GRIS
Kilometers	60.324
Inspection date	10/08/2026
Inspection place	Delotser Europark S.L.U

Damage assessment

Type	Element	Repair Type
Faltante	Libro mantenimiento -	Replace
Exterior	Repair Rear bumper (lower area)	Repair
Exterior	Repair Tailgate/boot lid trim	Repair
Exterior	Repair Windscreen glass	Repair
Exterior	Zaragoza center labor	Paint
Exterior	Painting: Zaragoza center	Paint
Exterior	Rear right wing w/ sill panel Repair (S=0) (L=1)	Paint
Exterior	Rear left wing w/ sill panel Repair (S=0) (L=1)	Paint
Exterior	Rear bumper (lower area) Repair (S=2) (L=0) Bodywo	Paint

- *Valuation system used: GT Estimate*
- *This appraisal is subject to hidden damage or previous repairs, not visible at the time of the inspection carried out withou disassembly and conformity of the parts according to the model and the return protocol*

Report signatures

En Castellar del Vallès a 11 de agosto de 2026



Assessor: Pericial Técnica, SCP

En MADRID a 11 de agosto de 2026

CED Spain Technical Department

In compliance with Art. 335.2 of the L.E.C. 1/2000 of January 7, the Inspector who signs this report declares under oath or promise to tell the truth, that he has acted with the greatest possible objectivity, taking into consideration both what may favor and what may cause harm to any of the parties, and that he is aware of the criminal sanctions that he could incur if he fails to fulfill his duty as Inspector

COMMERCIAL Photo Report








COMMERCIAL Photo Report

















COMMERCIAL Photo Report











DAMAGES Photo Report



Daño Exterior



Daño Exterior



Daño Exterior



Daño Exterior



Daño Exterior



Daño Exterior

DAMAGES Photo Report



Daño Exterior



Daño Exterior



Daño Exterior



Daño Exterior



Daño Exterior



Daño Exterior

DAMAGES Photo Report



Daño Exterior



Daño Exterior



Daño Exterior



Daño Exterior



Daño Exterior



Daño Interior

DAMAGES Photo Report



Daño Interior



Faltante